

PRE-SHIPMENT INSPECTION REPORT									
Client:					OVERALL RESULT		FAIL		
Report number:									
Inspection Date:	25.12.2020								
GENERAL INFORMATION									
Client:	PrC								
Supplier:	Le								
Factory:	k								
Product Name:	TWS Earphones								
P.O.#:	62								
Item#:	HB-8 white, black								
Order Quantity:	2000; 1000								
Finished Quantity:	2000; 1000								
Inspected Quantity:	70								
Destination country:									
Re-Inspection:									
Reference for inspection:	Approval sample		Product Specification						
	PO	PI	Packaging spec.						
	SOP: WINS-SOP-B202, WINS-SOP-A701								
Inspection location:	PRC, GUANGDONG, SHENZHEN, BAOAN, GUSHU								
INSPECTION SUMMARY									
					PASS	PENDING	FAIL	Not Applicable	
1. General Defects(AQL) and Remarks					X				
2. Quantity check					X				
3. Printings check(Shipping marks/Artworks/Labels)							X		
4. Package check							X		
5. Readings check(Barcodes / QR Codes / Serial ?)							X		
6. Measurements						X			
7. Visual and on-Site tests						X			
8. Customer's special requirements									
SAMPLING SIZE									
AQL ANSI/ASQ Z1.4-2008	Defects			Tests			Checks		
	Accepted	Actual	Result	Accepted	Actual	Result	Accepted	Actual	Result
Critical	0	0	PASS	0	0	PASS	0	0	PASS
Major	5	0	PASS	0	0	PASS	0	0	PASS
Minor	7	14	PASS	0	0	PASS	0	0	PASS
Summary									
1. GENERAL DEFECTS AND REMARKS									
Defects description:							Critical	Major	Minor
1	Glue mark								1
Total found:									
1-1. DEFECT PICTURES									
1	Scratch								
INSPECTORS REMARKS FOR CLIENTS CONSIDERATION									
1	The sound quality is not stable								
2	Connection and sound between left right earphones not synchronized								
OVERALL INSPECTION RESULT:					PENDING				
NOTICE:									
Abbreviation used in report: "MB" - Master box									
"IB" - Inner box									
"GB" - Gift box									

2. QUANTITY CHECK																						
Model number	Ordered	Actual	Master box	Inner box in master box	Gift box in inner box	Total gross weight	Total volume	Result														
HB-8 White	2000	20	20	5	20			PASS														
HB-8 Black	1000	10	10	5	20			PASS														
Result:		PASS																				
Remark:																						
3. PRINTINGS - SHIPPING MARKS / ARTWORKS / LABELS																						
Model number	Master box	Inner box	Gift box	Unit	User manual	Warranty card	Pantone	Result														
HB-8 White	Conform	Conform	Conform	Conform	Conform	Conform		PASS														
HB-8 Black	Conform	Conform	Conform	Conform	Conform	Conform		PASS														
Result:		PENDING																				
Remark:																						
4. PACKAGE CHECK																						
Model number	HB-8														Result							
	Master box					Inner box					Gift box											
SIZE	Actual	L	467	W	386	H	465	Inner box	L	435	W	362	H	85	Gift box	L	160	W	69	H	41	FAIL
	Marked	L	450	W	380	H	500		L	440	W	370	H	90		L		W		H		
GROSS WEIGHT	Actual	15985					3110					242,5				PASS						
	Marked	16000					3000															
NETT WEIGHT	Actual	15470					2790					158,5				PASS						
	Marked	15000					2800															
Carton thickness		6,0					2,8					2,1				PASS						
Carton layer		5					3					1				PASS						
Type of Seaming		Tape					Tape					Security stiker				PASS						
Result:		FAIL																				
Remark:		The diffence in real leight and marked weigth is more then 5%																				
5. READINGS CHECK - BARCODE S / QR CODES / SERIAL NUMBERS																						
Model number	HB-518 Black														Result							
	Master box					Inner box					Gift box											
BAR CODE	Actual						46100507					4610059				PASS						
	Marked						46100507					4610050										
	Provided																					
QR CODE												HB-18				PASS						
SERIAL NUMBER																PASS						
S/N RANGE																PASS						
Model number	HB-8 White														Result							
	Master box					Inner box					Gift box											
BAR CODE	Actual											46704290				PASS						
	Marked						0704184					461005070										
	Provided																					
QR CODE																FAIL						
SERIAL NUMBER																PASS						
S/N RANGE																PASS						
Result:		FAIL																				
Remark:																						

8. CUSTOMER'S SPECIAL REQUIREMENTS

	Check item	Description	Result
	Result:		
	Remark:		